

P4101 - □□□□ PT1000 -30 □+60°C 4-20mA□□

□□: P4101

□□□□□□PT1000□□□□□□□□□□
□□PT1000□□□□□□□□□□



□□□□

| | |
|--------------|----------------------------------|
| □□ | 4-20mA |
| □□□□ | □□ |
| □□□□ | □□PT1000□□□□ |
| □□ | □□ |
| □□□□□□ | ±0.3°C |
| 4-20mA□□□□□□ | -30 to +60°C |
| □□□□ | -30 to +80°C |
| □□□□ - □□□□ | 4-20mA |
| □□□□□□□□ | >24mA |
| □□□□□□□□ | <3.5mA |
| IP□□□□ | IP65 |
| □□ | 9-30Vdc□□□□24V |
| □□ | 88.5 x 117 x 39.5 mm (W x H x D) |
| □□ | □□ 125g |
| □□□□ | 3 □ |